





- 92% OF ALL GOLF SHOTS LAND WITHIN A 15 DEG. ANGLE EITHER SIDE OF THE INTENDED PLAYLINE
- WHERE A BOUNDARY,
 PARTICULARLY A SENSITIVE ONE LIKE
 HOUSING PLOTS OR SURROUNDING
 ROADS ARE VISIBLE FROM THE TEE THE
 IMPACT ON A GOLFERS PSYCHOLOGY
 CAN BE QUITE EXTREME
- IF A SENSITIVE BOUNDARY COMES INTO PLAY ALLOWANCES BOTH IN TERMS OF ENLARGING THE MARGINS AS WELL AS PROVIDING SOME SOLUTIONS TO THE PROBLEM IN THE MID TO LONG TERM (ie PLANTING) SHOULD BE INCLUDED
- THE ORIENTATION OF TEES HAVE
 A DRAMATIC IMPACT ON A GOLFERS
 ALIGNMENT. A GOLFER HAS ONLY TO
 BE MISALIGNED BY 5 OR 6 DEG. FROM
 THE CENTRE OF THE FAIRWAY TO MISS
 ALTOGETHER A 40 MTR WIDE FAIRWAY
- THE ABOVE GUIDELINES HAVE
 BEEN EXTRACTED FROM THE EIGCA
 STANDARDS ON GOLF COURSE SAFETY
 MARGINS





Sherborne, Dorset f: 01895 431333 e.enguiries@woodland.uk.co

e.enquiries@woodland.uk.com	
project:	drawing title:
Remodel	
date:	PROPOSED
12.04.2011	14th HOLE SAFETY
scale:	PLAN
1:500	

